
Disclaimer



Créaset/Hecht can take the measures for you. Final confirmation is always under client responsability. Without any comment, the client tacitly confirms the dimensions for production.



For fleet placement, the vehicules must be cleaned and stored in an inner heated place between 15° and 25°C and without dust minimum 24h prior placement.



To ensure the best long-term result, we need to respect production processes. Considering the combination of different raw materials, production can take several days. Créaset/Hecht will always inform the best delivery date. Shorten the production time for faster delivery is under client responsability.



Every glue, vinyl, laminate reacts in different way to weather temparature by contractions or dilations. Those reactions are also influenced by the colors printed and the combination of different raw material. Créaset/Hecht is not responsible in case of support damages due to thermal variation combined to construction specificity of the support.



Working over 2.5m requires specific lader, scafholder or cherry-picker, pending on the working area. For our workers safety, Créaset/Hecht keeps the right to choose the best/safer solution.



A power supply must be available maximum 10m away from the placement site.



Working area must be clean and empty at team arrival. If not, cleaning process or second venue will be charged to the client.



At least one member of client's team is on site and has full knowledge of the briefing.



Créaset/Hecht is not responsible of placement delay due to weather conditions. If the client requires the placement despite the technical advisory, Créaset/Hecht decline any responsibility of product stability. Workers safety always predominate on delivery date.

